




TLE PHO - Thursday, February 16, 2017 1:06:38 PM (Yard # AR - LITTLE ROCK)

User Name	Yard # AR - LITTLE ROCK
User #	00
Form Started	2/16/2017 1:06:38 PM
Form Submitted	2/16/2017 1:38:05 PM
Completion Date	Thursday, February 16, 2017
Completed By:	John Doe
Lot Number	12345678
Claim Number	ABCD-12-3456789
License Plate	123 ABC 12. 04/17

VIN # Number and picture



Year	11
Make	Chevrolet
Model	Cruze
Odometer	95937
Body Style	4 DOOR
Color	WHITE
Engine	4
Transmission	Automatic
Drivetrain	2WD

EXTERIOR

Exterior Automatic Headlights, Fog Lights, Power Mirrors, Tinted Glass, Wheels - Alum/Alloy

INTERIOR	
Interior	Audio - AM / FM, Audio - CD Player, Air Conditioning - Automatic, Air Conditioning - Manual , Audio - Preminim Sound System, Cruise Control, Rear Window Defogger, Power Windows, Power Locks, Seats - First Row Buckets, Seats - Second Row Bench , Tilt Steering Manual
MECHANICAL	
Mechanical	Power Brakes, Power Steering, ABS Brake Systems, Traction Control
SAFETY	
Safety	Air Bag - Driver Side , Air Bag - Front Side, Air Bag - Head, Air Bag - Passenger Side, Air Bag Second Row Side, Air Bag - Side Air Bags - Curtain, Air Bag - Side Air Bags - Torso, Anti-Theft - System, Tire Inflation/Pressure Monitor
INTERIOR	
SEATS: Seats, seat belts, seat backs and headrests. Include third seats in van's, SUV's and wagons.	4 - Very Good
CARPET: Includes molded inserts. Includes trunk carpet and floor mats	4 - Very Good
HEADLINER: Headliner and visors	3 - Good
DOORS / INTERIOR PANELS: All inner door panels. Trunk panels.	4 - Very Good
DASH/CONSOLE: Center and overhead console	4 - Very Good
GLASS: Glass only. Does not include moldings, aftermarket tint, or plastic convertible glass.	4 - Very Good
EXTERIOR	
BODY: Outside body panels, including truck beds. Does not include bumpers or grilles. Ding = golfball size or smaller	3 - Good
PAINT: All body panels, including truck beds. Does not include paint on bumpers, trim or spoiler.	2 - Fair
TRIM: Major: grilles, bumpers, wheels, mirrors, body cladding, luggage racks; spoilers, running boards and roof racks. Minor: lamps, emblems, antennas, wheel covers and all outside moldings	3 - Good
VINYL OR CONVERTIBLE TOPS: Convertible roof including plastic back glass, simulated convertibles, landau and full vinyl top	3 - Good

MECHANICAL

ENGINE: If engine is inaccessible mark as Unknown 3 - Good

TRANSMISSION: If transmission is inaccessible mark as Unknown 2 - Fair

TIRES

TIRES: Rate tires independently, add ratings for each tire (4) to determine overall rating 3 - Good

Passenger front corner

[Image]



Driver front corner

[Image]



Driver rear corner

[Image]



Passenger rear corner

[Image]



Dash VIN

[Image]



Odometer:



Steering Wheel

[Image]



Console/Stereo Area

[Image]



Driver front seat area including carpet

[Image]



Driver rear seat area

[Image]



Passenger front seat area including carpet

[Image]



Passenger rear seat area

[Image]



Trunk Area

[Image]



Photo of damage

[Image]



Photo of damage

[Image]



Anything out of the ordinary for the vehicle. i.e. prior damage, aftermarket items, condition adjustments, etc

Additional Photos

Completed By: John Doe

Completed Date 2/16/17

EMAIL INSTRUCTIONS Once form completed and approved send to copart@com-search.com